MICHIGAN DEPARTMENT OF ENVIRONMENTAL QUALITY **DRINKING WATER LABORATORY**



USEPA Region V Drinking Water Cert. No. MI00003 P.O. Box 30270 Lansing, MI 48909

TEL: (517) 335-8184 FAX: (517) 335-8562 Sample Number LH55390

Official Laboratory Report

Report To:

JEFF MYERS

System Name/Owner:

WEST MIDLAND FAMILY CENTER

Collection Address: Collected By:

4011 W ISABELLA RD, SHEPHERD

JEFF MYERS

Township/Well#/Section:

GREENDALE/5/15

County:

Midland

Sample Point: Water System: **RAW**

Untreated Public Distribution System

WSSN/Pool ID:

2002156 TYPE II

Source:

Purpose:

Site Code:

Collector:

Public Water Supply Operator

Date Collected: Date Received: 11/30/2017

08:25 12:59

11/30/2017

Routine Monitoring

TESTING INFORMATION			REGULATORY INFORMATION			
Analyte Name	Result (mg/L)	Date Tested	RL (mg/L)	MCL/AL (mg/L)	Method	CAS#
Arsenic	0.007	12/01/2017	0.002	0.010	EPA 200.8	7440-38-2

The analyses performed by the MDEQ Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below:

> Midland County Health Dept. 220 West Ellsworth Midland, MI 48640-5194 989 832-6679

CAS#: Chemical Abstract Service Registry Number

MCL: Maximum Contaminant Level AL: Action Level

RL: Reporting Limit

mg/L: milligrams / Liter (ppm)

ppm: parts per million MPN: Most Probable Number CFU: Colony Forming Unit

Laboratory Contact: Scott Hayward

1:33:39PM

MICHIGAN DEPARTMENT OF ENVIRONMENTAL QUALITY DRINKING WATER LABORATORY



USEPA Region V Drinking Water Cert. No. MI00003 P.O. Box 30270

Lansing, MI 48909 TEL: (517) 335-8184 FAX: (517) 335-8562

Sample Number LH55391

Official Laboratory Report

Report To:

JEFF MYERS

System Name/Owner:

WEST MIDLAND FAMILY CENTER

Collection Address:

4011 W ISABELLA RD, SHEPHERD

WSSN/Pool ID:

2002156 TYPE II

Collected By:

TO THE TOTAL PROPERTY OF THE P

Source: Site Code:

Township/Well#/Section:

GREENDALE/5/15

Collector:

Public Water Supply Operator

County:

Midland

Date Collected:

11/30/2017 07:15

Sample Point:

KITCHEN

Date Received:

11/30/2017 12:59

Water System:

Untreated Public Distribution System

Purpose:

Routine Monitoring

TESTING INFORMATION			REGULATORY INFORMATION			
Analyte Name	Result (mg/L)	Date Tested	RL (mg/L)	MCL/AL (mg/L)	Method	CAS#
Arsenic	0.002	12/01/2017	0.002	0.010	EPA 200.8	7440-38-2

The analyses performed by the MDEQ Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below:

Midland County Health Dept. 220 West Ellsworth Midland, MI 48640-5194 989 832-6679

CAS#: Chemical Abstract Service Registry Number MCL: Maximum Contaminant Level

AL: Action Level RL: Reporting Limit mg/L : milligrams / Liter (ppm) ppm : parts per million

MPN : Most Probable Number CFU : Colony Forming Unit Laboratory Contact: Scott Hayward