

**MICHIGAN DEPARTMENT OF ENVIRONMENTAL QUALITY
DRINKING WATER LABORATORY**

USEPA Region V Drinking Water Cert. No. MI00003
P.O. Box 30270
Lansing, MI 48909
TEL: (517) 335-8184
FAX: (517) 335-8562



**Sample Number
LH88621**

Official Laboratory Report

Report To: JEFF MYERS
4011 W ISABELLA RD
SHEPHERD MI

System Name/Owner:	WEST MIDLAND FAMILY CENTER	WSSN/Pool ID:	2002156
Collection Address:	4011 W ISABELLA RD,SHEPHERD	Source:	TYPE II
Collected By:	JEFF MYERS	Site Code:	
Township/Well#/Section:	GREENDALE/5/15	Collector:	Public Water Supply Operator
County:	Midland	Date Collected:	06/25/2018 09:00
Sample Point:	RAW	Date Received:	06/25/2018 12:46
Water System:	Untreated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION			REGULATORY INFORMATION			
Analyte Name	Result (mg/L)	Date Tested	RL (mg/L)	MCL/AL (mg/L)	Method	CAS #
Arsenic	0.010	06/26/2018	0.002	0.010	EPA 200.8	7440-38-2

The analyses performed by the MDEQ Drinking Water Laboratory were conducted using methods approved by the U .S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below:

**Midland County Health Dept.
220 West Ellsworth
Midland, MI 48640-5194
989 832-6679**

CAS# : Chemical Abstract Service Registry Number
MCL : Maximum Contaminant Level
AL : Action Level
RL : Reporting Limit

mg/L : milligrams / Liter (ppm)
ppm : parts per million
MPN : Most Probable Number
CFU : Colony Forming Unit

Laboratory Contact: Scott Hayward

**MICHIGAN DEPARTMENT OF ENVIRONMENTAL QUALITY
DRINKING WATER LABORATORY**

USEPA Region V Drinking Water Cert. No. MI00003
P.O. Box 30270
Lansing, MI 48909
TEL: (517) 335-8184
FAX: (517) 335-8562



**Sample Number
LH88622**

Official Laboratory Report

Report To: JEFF MYERS
4011 W ISABELLA RD
SHEPHERD MI 48883

System Name/Owner:		WSSN/Pool ID:	2002156
Collection Address:	4011 W ISABELLA RD,SHEPHERD	Source:	TYPE II
Collected By:	JEFF MYERS	Site Code:	
Township/Well#/Section:	GREENDALE/5/15	Collector:	Public Water Supply Operator
County:	Midland	Date Collected:	06/25/2018 09:07
Sample Point:	RO	Date Received:	06/25/2018 12:46
Water System:	Untreated Public Distribution System	Purpose:	Other

TESTING INFORMATION			REGULATORY INFORMATION			
Analyte Name	Result (mg/L)	Date Tested	RL (mg/L)	MCL/AL (mg/L)	Method	CAS #
Arsenic	Not detected	06/26/2018	0.002	0.010	EPA 200.8	7440-38-2

The analyses performed by the MDEQ Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below:

**Midland County Health Dept.
220 West Ellsworth
Midland, MI 48640-5194
989 832-6679**

CAS# : Chemical Abstract Service Registry Number
MCL : Maximum Contaminant Level
AL : Action Level
RL : Reporting Limit

mg/L : milligrams / Liter (ppm)
ppm : parts per million
MPN : Most Probable Number
CFU : Colony Forming Unit

Laboratory Contact: Scott Hayward

**MICHIGAN DEPARTMENT OF ENVIRONMENTAL QUALITY
DRINKING WATER LABORATORY**

USEPA Region V Drinking Water Cert. No. MI00003
P.O. Box 30270
Lansing, MI 48909
TEL: (517) 335-8184
FAX: (517) 335-8562



**Sample Number
LH88623**

Official Laboratory Report

Report To: JEFF MYERS
4011 W ISABELLA RD
SHEPHERD MI 48883

System Name/Owner:	WEST MIDLAND FAMILY CENTER	WSSN/Pool ID:	2002156
Collection Address:	4011 W ISABELLA RD,SHEPHERD	Source:	TYPE II
Collected By:	JEFF MYERS	Site Code:	
Township/Well#/Section:	GREENDALE/5/15	Collector:	Public Water Supply Operator
County:	Midland	Date Collected:	06/25/2018 09:05
Sample Point:	KITCHEN	Date Received:	06/25/2018 12:46
Water System:	Untreated Public Distribution System	Purpose:	Other

TESTING INFORMATION			REGULATORY INFORMATION			
Analyte Name	Result (mg/L)	Date Tested	RL (mg/L)	MCL/AL (mg/L)	Method	CAS #
Arsenic	0.006	06/26/2018	0.002	0.010	EPA 200.8	7440-38-2

The analyses performed by the MDEQ Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below:

**Midland County Health Dept.
220 West Ellsworth
Midland, MI 48640-5194
989 832-6679**

CAS# : Chemical Abstract Service Registry Number
MCL : Maximum Contaminant Level
AL : Action Level
RL : Reporting Limit

mg/L : milligrams / Liter (ppm)
ppm : parts per million
MPN : Most Probable Number
CFU : Colony Forming Unit

Laboratory Contact: Scott Hayward

**MICHIGAN DEPARTMENT OF ENVIRONMENTAL QUALITY
DRINKING WATER LABORATORY**

USEPA Region V Drinking Water Cert. No. MI00003
P.O. Box 30270
Lansing, MI 48909
TEL: (517) 335-8184
FAX: (517) 335-8562



**Sample Number
LH88625**

Official Laboratory Report

Report To: JEFF MYERS
4011 W ISABELLA RD
SHEPHERD MI 48883

System Name/Owner:	WEST MIDLAND FAMILY CENTER	WSSN/Pool ID:	2002156
Collection Address:	4011 W ISABELLA RD,SHEPHERD	Source:	TYPE II
Collected By:	JEFF MYERS	Site Code:	
Township/Well#/Section:	GREENDALE/5/15	Collector:	Other
County:	Midland	Date Collected:	06/25/2018 09:15
Sample Point:	RAW	Date Received:	06/25/2018 12:47
Water System:	Untreated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION			REGULATORY INFORMATION			
Analyte Name	Result (mg/L)	Date Tested	RL (mg/L)	MCL/AL (mg/L)	Method	CAS #
Chloride	115	06/25/2018	4		SM 4500-CI E	7647-14-5
Fluoride	0.56	06/25/2018	0.1	4.0	SM 4500 FC	16984-48-8
Hardness as CaCO3	634	06/25/2018	20		SM 2340 C	HARD-00-C
Iron (automated)	0.9	06/25/2018	0.1		SM 3500 FeB	7439-89-6
Nitrate as N	Not Detected	06/25/2018	0.4	10	10-107-04-2-A	14797-55-8
Nitrite as N	Not detected	06/25/2018	0.05	1	10-107-04-2-A	14797-65-0
Sodium (automated)	107	06/25/2018	5		SM 3500 NaB	7440-23-5
Sulfate	589	06/25/2018	10		SM 4500 SO4E	14808-79-8

The analyses performed by the MDEQ Drinking Water Laboratory were conducted using methods approved by the U .S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below:

**Midland County Health Dept.
220 West Ellsworth
Midland, MI 48640-5194
989 832-6679**

CAS# : Chemical Abstract Service Registry Number
MCL : Maximum Contaminant Level
AL : Action Level
RL : Reporting Limit

mg/L : milligrams / Liter (ppm)
ppm : parts per million
MPN : Most Probable Number
CFU : Colony Forming Unit

Laboratory Contact: Scott Hayward