

Official Laboratory Report

Report To: JEFF MYERS
SAME
MI

Sample ID: LI59060
Work Order: 90804404_01

System Name/Owner:	WEST MIDLAND FAMILY CENTER	WSSN/Pool ID:	20021-56
Collection Address:	4011 W ISABELLA RD,SHEPHERD	Source:	TYPE II
Collected By:	JEFF MYERS	Site Code:	
Township/Well#/Section:	GREENDALE/#5/15	Collector:	Other
County:	Midland	Date Collected:	08/26/2019 08:10
Sample Point:	COTTAGE	Date Received:	08/26/2019 11:08
Water System:	Untreated Public Distribution System	Purpose:	Other

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	0.07	mg/L	0.05	08/28/2019	1.3	EPA 200.8	7440-50-8
Lead	0.005	mg/L	0.001	08/28/2019	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Midland County Health Dept.
220 West Ellsworth
Midland, MI 48640-5194
989 832-6679

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

Official Laboratory Report

Report To: JEFF MYERS
SAME
MI

Sample ID: LI59061

Work Order: 90804404_02

System Name/Owner: JEFF MYERS
Collection Address: 4011 W ISABELLA RD,SHEPHERD
Collected By: JEFF MYERS
Township/Well#/Section: GREENDALE/#5/15
County: Midland
Sample Point: NEW GYM FOUNTAIN
Water System: Untreated Public Distribution System

WSSN/Pool ID: 20021-56
Source: TYPE II
Site Code:
Collector: Other
Date Collected: 08/26/2019 08:05
Date Received: 08/26/2019 11:08
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	0.05	mg/L	0.05	08/28/2019	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	08/28/2019	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Midland County Health Dept.
220 West Ellsworth
Midland, MI 48640-5194
989 832-6679

Official Laboratory Report

Report To: JEFF MYERS
SAME
MI

Sample ID: LI59062
Work Order: 90804404_03

System Name/Owner: WEST MIDLAND FAMILY CENTER
Collection Address: 4011 W ISABELLA RD, SHEPHERD
Collected By: JEFF MYERS
Township/Well#/Section: GREENDALE/#5/15
County: Midland
Sample Point: CLASSROOM 116
Water System: Untreated Public Distribution System

WSSN/Pool ID: 20021-56
Source: TYPE II
Site Code:
Collector: Other
Date Collected: 08/26/2019 08:00
Date Received: 08/26/2019 11:08
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	0.26	mg/L	0.05	08/28/2019	1.3	EPA 200.8	7440-50-8
Lead	0.005	mg/L	0.001	08/28/2019	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Midland County Health Dept.
220 West Ellsworth
Midland, MI 48640-5194
989 832-6679

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

Official Laboratory Report

Report To: JEFF MYERS
SAME
MI

Sample ID: LI59063
Work Order: 90804404_04

System Name/Owner: JEFF MYERS
Collection Address: 4011 W ISABELLA RD,SHEPHERD
Collected By: JEFF MYERS
Township/Well#/Section: GREENDALE/#5/15
County: Midland
Sample Point: DAYCARE 207
Water System: Untreated Public Distribution System

WSSN/Pool ID: 20021-56
Source: TYPE II
Site Code:
Collector: Other
Date Collected: 08/26/2019 08:05
Date Received: 08/26/2019 11:08
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	08/28/2019	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	08/28/2019	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Midland County Health Dept.
220 West Ellsworth
Midland, MI 48640-5194
989 832-6679

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



MICHIGAN DEPARTMENT OF
ENVIRONMENT, GREAT LAKES, AND ENERGY

MICHIGAN DEPARTMENT OF
ENVIRONMENT, GREAT LAKES, AND ENERGY
DRINKING WATER LABORATORY
USEPA Region V Drinking Water Cert. No. MI00003

P.O. Box 30270
Lansing, MI 48909
TEL: (517) 335-8184
FAX: (517) 335-8562

Official Laboratory Report

Report To: JEFF MYERS
SAME
MI

Sample ID: LI59064
Work Order: 90804404_05

System Name/Owner: WEST MIDLAND FAMILY CENTER
Collection Address: 4011 W ISABELLA RD, SHEPHERD
Collected By: JEFF MYERS
Township/Well#/Section: GREENDALE/#5/15
County: Midland
Sample Point: OLD GYM FOUNTAIN
Water System: Untreated Public Distribution System

WSSN/Pool ID: 20021-56
Source: TYPE II
Site Code:
Collector: Other
Date Collected: 08/26/2019 08:05
Date Received: 08/26/2019 11:08
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	08/28/2019	1.3	EPA 200.8	7440-50-8
Lead	0.005	mg/L	0.001	08/28/2019	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Midland County Health Dept.
220 West Ellsworth
Midland, MI 48640-5194
989 832-6679

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

Official Laboratory Report

Report To: JEFF MYERS
SAME
MI

Sample ID: LI59065
Work Order: 90804404_06

System Name/Owner:	WEST MIDLAND FAMILY CENTER	WSSN/Pool ID:	20021-56
Collection Address:	4011 W ISABELLA RD, SHEPHERD	Source:	TYPE II
Collected By:	JEFF MYERS	Site Code:	
Township/Well#/Section:	GREENDALE/#5/15	Collector:	Other
County:	Midland	Date Collected:	08/26/2019 08:00
Sample Point:	HALL WAY BY 119A	Date Received:	08/26/2019 11:08
Water System:	Untreated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	0.55	mg/L	0.05	08/28/2019	1.3	EPA 200.8	7440-50-8
Lead	0.002	mg/L	0.001	08/28/2019	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Midland County Health Dept.
220 West Ellsworth
Midland, MI 48640-5194
989 832-6679

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane