

MICHIGAN DEPARTMENT OF ENVIRONMENTAL QUALITY

DRINKING WATER LABORATORY

USEPA Region V Drinking Water Cert. No. MI00003

P.O. Box 30270

Lansing, MI 48909

TEL: (517) 335-8184

FAX: (517) 335-8562



Sample Number

LH88621

Official Laboratory Report

Report To: JEFF MYERS
4011 W ISABELLA RD
SHEPHERD MI

System Name/Owner: WEST MIDLAND FAMILY CENTER
Collection Address: 4011 W ISABELLA RD,SHEPHERD
Collected By: JEFF MYERS
Township/Well#/Section: GREENDALE/5/15
County: Midland
Sample Point: RAW
Water System: Untreated Public Distribution System

WSSN/Pool ID: 2002156
Source: TYPE II
Site Code:
Collector: Public Water Supply Operator
Date Collected: 06/25/2018 09:00
Date Received: 06/25/2018 12:46
Purpose: Routine Monitoring

TESTING INFORMATION			REGULATORY INFORMATION			
Analyte Name	Result (mg/L)	Date Tested	RL (mg/L)	MCL/AL (mg/L)	Method	CAS #
Arsenic	0.010	06/26/2018	0.002	0.010	EPA 200.8	7440-38-2

The analyses performed by the MDEQ Drinking Water Laboratory were conducted using methods approved by the U .S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below:

**Midland County Health Dept.
220 West Ellsworth
Midland, MI 48640-5194
989 832-6679**

CAS# : Chemical Abstract Service Registry Number
MCL : Maximum Contaminant Level
AL : Action Level
RL : Reporting Limit

mg/L : milligrams / Liter (ppm)
ppm : parts per million
MPN : Most Probable Number
CFU : Colony Forming Unit

Laboratory Contact: Scott Hayward



MICHIGAN DEPARTMENT OF ENVIRONMENTAL QUALITY
DRINKING WATER LABORATORY

USEPA Region V Drinking Water Cert. No. MI00003
P.O. Box 30270
Lansing, MI 48909
TEL: (517) 335-8184
FAX: (517) 335-8562

Sample Number
LH88622

Official Laboratory Report

Report To: JEFF MYERS
4011 W ISABELLA RD
SHEPHERD MI 48883

System Name/Owner:
Collection Address: 4011 W ISABELLA RD,SHEPHERD
Collected By: JEFF MYERS
Township/Well#/Section: GREENDALE/5/15
County: Midland
Sample Point: RO
Water System: Untreated Public Distribution System

WSSN/Pool ID: 2002156
Source: TYPE II
Site Code:
Collector: Public Water Supply Operator
Date Collected: 06/25/2018 09:07
Date Received: 06/25/2018 12:46
Purpose: Other

TESTING INFORMATION			REGULATORY INFORMATION			
Analyte Name	Result (mg/L)	Date Tested	RL (mg/L)	MCL/AL (mg/L)	Method	CAS #
Arsenic	Not detected	06/26/2018	0.002	0.010	EPA 200.8	7440-38-2

The analyses performed by the MDEQ Drinking Water Laboratory were conducted using methods approved by the U .S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below:

Midland County Health Dept.
220 West Ellsworth
Midland, MI 48640-5194
989 832-6679

CAS# : Chemical Abstract Service Registry Number
MCL : Maximum Contaminant Level
AL : Action Level
RL : Reporting Limit

mg/L : milligrams / Liter (ppm)
ppm : parts per million
MPN : Most Probable Number
CFU : Colony Forming Unit

Laboratory Contact: Scott Hayward

MICHIGAN DEPARTMENT OF ENVIRONMENTAL QUALITY

DRINKING WATER LABORATORY

USEPA Region V Drinking Water Cert. No. MI00003

P.O. Box 30270

Lansing, MI 48909

TEL: (517) 335-8184

FAX: (517) 335-8562



Sample Number

LH88623

Official Laboratory Report

Report To: JEFF MYERS
4011 W ISABELLA RD
SHEPHERD MI 48883

System Name/Owner: WEST MIDLAND FAMILY CENTER
Collection Address: 4011 W ISABELLA RD,SHEPHERD
Collected By: JEFF MYERS
Township/Well#/Section: GREENDALE/5/15
County: Midland
Sample Point: KITCHEN
Water System: Untreated Public Distribution System

WSSN/Pool ID: 2002156
Source: TYPE II
Site Code:
Collector: Public Water Supply Operator
Date Collected: 06/25/2018 09:05
Date Received: 06/25/2018 12:46
Purpose: Other

TESTING INFORMATION			REGULATORY INFORMATION			
Analyte Name	Result (mg/L)	Date Tested	RL (mg/L)	MCL/AL (mg/L)	Method	CAS #
Arsenic	0.006	06/26/2018	0.002	0.010	EPA 200.8	7440-38-2

The analyses performed by the MDEQ Drinking Water Laboratory were conducted using methods approved by the U .S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below:

**Midland County Health Dept.
220 West Ellsworth
Midland, MI 48640-5194
989 832-6679**

CAS# : Chemical Abstract Service Registry Number
MCL : Maximum Contaminant Level
AL : Action Level
RL : Reporting Limit

mg/L : milligrams / Liter (ppm)
ppm : parts per million
MPN : Most Probable Number
CFU : Colony Forming Unit

Laboratory Contact: Scott Hayward